

FIGURE 1  
(PRIOR ART)




FIGURE 2




Figure 3

400

220

FLASH

BOOT LOADER PROGRAM

0x00400000

DEFAULT  
APPLICATION  
PROGRAM

0x00000000

FIGURE 4

500




FIGURE 5

2025 RELEASE UNDER E.O. 14176




FIGURE 6

